


OTB-358N



Measurements List of A, B & C (P : Number of terminals) Special Order 13P~15P

P	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
A	45	61	77	93	109	125	141	157	173	189	205	221	237	253	269
B	32	48	64	80	96	112	128	144	160	176	192	208	224	240	256
C	19	35	51	67	83	99	115	131	147	163	179	195	211	227	243